

# Destructive Evaluation and Extended Fatigue Testing of a Retired Passenger Aircraft (B727)

## Deliverables Summary (through Q9)

- Detailed Work Plan Report (Q9)
- Aircraft Information Report
- Target Area Report
- Field Inspection Report
- Specimen Removal Report
- Pre-Teardown Inspection Report
- Test Plan Analysis
- Overview of Teardown Procedure
- Damage Characterization Report (Q9)
- Data Analysis Report (Q9)
- Inspection Capability Report (Q9)

## Database Documentation

- Q11 Version Documentation